



DoW Lock Program

NAVFAC Engineering and Expeditionary Warfare Center

1100 23rd Avenue, Port Hueneme, CA 93043

(800) 290-7607 or (805) 982-1212


<https://locks.navfac.navy.mil>

High Security Padlock Identification


833C versus 951 Models

The 833C (S&G) and 951 (S&G, PacLock) model High Security Padlocks have specific parts that if installed in the wrong model will cause malfunctions. The cap, cam, and key length from the shoulder are the main differences. This document will help identify all differences between these models.

833C and 951 Marking and Casting Differences



833C and 951 partially disassembled




833C and 951 fully disassembled



833C versus 951 Cap

DO NOT NTERCHANGE




833C versus 951 Cam

DO NOT NTERCHANGE



833C versus 951 keys

The key identifies correct cylinder



833C cylinder key has a longer shoulder

Quick Check of shoulder length



Key Cuts facing up, shoulder against the edge of the Key Tag.